
TO-LET
79299449807


KIRLOSKAR LAYOUT
Kruthika Hospital
C.R building
MEI Layout Park
VESHWARAIAH LAYOUT
Bagalgunte Police Station
NAGASANDRA
Google

Bengaluru
Karnataka
India
31°C
88°F
2021-03-07(Sun) 04:03(PM)


Sapthagiri College of Engineering, Bengaluru
Siddedahalli
Bonemill Bu
MEI PARK
Government Hospital Bagalagunte (Primary...
Bagalgunte Police Station
APURA
Google


Siddeshwara Layout Rd, Siddeshwar Layout, Soundarya Layout, Bengaluru, Karnataka 560090, India
Bengaluru
Karnataka
India
27°C
81°F
2021-07-17(Sat) 01:55(PM)

Replace of Bore well in Mahakali and Sangalagatti ward, No-14.





ಸಿಂಧನೂರು ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಧಿಕಾರಿ

Bagalagunte Ward NO-14. of Borewell (1)



156, 1st Main Rd, Soundarya Layout, Bengaluru, Karnataka 560073, India

Bengaluru

Karnataka

India

2020-11-04(Wed) 12:00(PM)

28°C

82°F

Sapthagiri College of Engineering, Bengaluru
Siddeshwara Layout Rd, Siddeshwar Layout, Soundarya Layout, Bengaluru, Karnataka 560090, India
Bengaluru
Karnataka
India
2021-07-17(Sat) 01:55(PM)
27°C
81°F

Sapthagiri College of Engineering, Bengaluru
Siddeshwara Layout Rd, Siddeshwar Layout, Soundarya Layout, Bengaluru, Karnataka 560090, India
Bengaluru
Karnataka
India
2021-07-17(Sat) 01:56(PM)
27°C
81°F

Name of the Work: Maintenance and Repairs of Bore wells in Bagalagunte Ward No: 11.









ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ
ಬಿ. ದಾಸರಹಳ್ಳಿ

Photo of work in Mahaveer Boggalagunte Village

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ
ಪಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಬಿ.ಬಿ

Name of work: Maintenance and Repairs of Borewells in Bangalore North Taluk in No-14.





ಸಹಾಯಕ ಕಾರ್ಯ[illegible]
ಬಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಬಿ[illegible]

Name of Work :- maintenance and Repair of Borewell in Bagalagunte W: no-14.





Maintenance and Repairs of Borewell in Ward No:-14.





Sapthagiri College of Engineering, Bengaluru
Siddenahalli
Bonemill Bu
MEI PARK
Government Hospital Bagalagunte (Primary...
Bagalgunte Police Station
Google
Siddeshwara Layout, 2nd Cross, Sahyadri Layout, Siddeshwara Layout, Soundarya Layout, Bengaluru, Karnataka 560073, India
Bengaluru
Karnataka
India
26°C
79°F
2021-07-17(Sat) 09:52(AM)


2021-08-25(Wed) 04:36(PM)

Name of work :- Maintenance and Repair of Borewell at Bagalagunte, W. no-14.







Name of work :- Maintenance and Repairing of Bore well in Bagalgunte Ward No-174.











ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಿಬಿಎಂಪಿ.

Bore well in Bagalgunte





2020-11-04(Wed) 11:53(AM)
Sapthagiri Ho
Sapthag
Engineerin
SMS-Soundarya
Institute of
Siddahalli
MEI PA
SHIVASHAKTI
NAGAR
VISVESHWARAIA
LAYOUT
Google


Bonemill Bus Stop
Balaji Scan Centre
Police Station
Bagalagunte
Sub Post Office
BHUVANESHWARI
NAGAR
Google


3rd 'A'main, 2nd Cross Rd, MEI Layout, Bagalakunte, Bengaluru, Karnataka 560073, India
Bengaluru
Karnataka
India
2021-06-24(Thu) 08:13(AM)
23°C
73°F

(20)

Name of Work:- Maintance and Ryprirs of Bore well in Bagalagunte. W.No-14.